PRINTED: 11/20/2012 FORM APPROVED

Indiana State Department of Health

NAME OF PROVIDER OR SUPPLIER MARTIN COUNTY HEALTHCARE & REHABILITATION (X4) ID PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) (X5) INITIAL COMMENTS A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of Health.	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER IDENTIFICATION NUM			(X2) MULTIPLE CONSTRUCTION A. BUILDING B. WING		(X3) DATE SURVEY COMPLETED		
MARTIN COUNTY HEALTHCARE & REHABILITATION (X4) ID PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) (X5) COMPLETIX TAG (X6) INITIAL COMMENTS A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of	-				<u> </u>			
PREFIX TAG (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) K 000 INITIAL COMMENTS A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of	I MADTIN COLINTY HEALTHCADE & DEHABILITATION . I							
A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of	PREFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			PREFIX	(EACH CORRECTIVE ACTI CROSS-REFERENCED TO TI	(EACH CORRECTIVE ACTION SHOULD BE COMPI CROSS-REFERENCED TO THE APPROPRIATE DAT	
Survey Date: 11/15/12 Facility Number: 000571 Provider Number: 155374 AIM Number: 100266920 Surveyor: Lex Brashear, Life Safety Code Specialist At this Quality Assurance Walk-thru survey, Martin County Healthcare & Rehabilitation Center was found in compliance with 410 IAC 16.2-3.1-19(ff). This one story facility was determined to be of Type V (000) construction and was fully sprinklered. The facility has a fire alarm system with hard wired smoke detectors in the corridors, spaces open to the corridors, and in all resident sleeping rooms. The facility has a capacity of 62 and had a census of 24 at the time of this survey. The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage. All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered. All areas providing facility services were sprinklered covertion to etatached shed used as an employee only smoke shack. Quality Review by Robert Booher, Life Safety Code Specialist-Medical Surveyor on 11/16/12.	K 000	INITIAL COMMENTS A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of Health. Survey Date: 11/15/12 Facility Number: 000571 Provider Number: 155374 AIM Number: 100266920 Surveyor: Lex Brashear, Life Safety Code Specialist At this Quality Assurance Walk-thru survey, Martin County Healthcare & Rehabilitation Center was found in compliance with 410 IAC 16.2-3.1-19(ff). This one story facility was determined to be of Type V (000) construction and was fully sprinklered. The facility has a fire alarm system with hard wired smoke detectors in the corridors, spaces open to the corridors, and in all resident sleeping rooms. The facility has a capacity of 62 and had a census of 24 at the time of this survey. The facility was found in compliance with state law in regard to sprinkler coverage and smoke detector coverage. All areas where residents have customary access were sprinklered. All areas providing facility services were sprinklered, except one detached shed used as an employee only smoke shack. Quality Review by Robert Booher, Life Safety			K 000			

Indiana State Department of Health

TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE